

THE HEIGHT-OF-CUT GAUGE. ESSENTIAL FOR MAINTENANCE.

MEASURE YOUR HEIGHT OF CUT.



Height of cut gauge for precision setting of mowers

- Essential workshop tool for bench setting the height of cut of mowing cutting units
- Use in conjunction with the Prism Gauge to set, monitor and control height of cut
- Measures to the ground surface of the bedknife the datum reference for cutting
- · Eliminates trial and error guesswork
- Accurate to .001 inch (0.0254mm)
- Digital read-out available in metric or imperial.



BUY BERNHARD. GET THE EDGE